


Wall Jamb



TROUBLESHOOTING

| TROUBLESHOOTING | |
|---|---|
| Symptom: Alignment | Recommended Action |
| 1. The top of the door panel is tilted away from the wall. | A. Remove the door panel from the top track and lower the roller that is closest to the wall. See step 17. |
| 2. The bottom of the door panel is tilted away from the wall. | A. Remove the door panel from the top track and raise the roller that is closest to the wall. See step 17. |
| 3. The door panel does not touch the bumper. | A. Determine whether door panel top or bottom is closer to the wall and then adjust the roller closest to the wall. |
| 4. The wall jamb is not flush against the wall. | A. Check that the top and bottom tracks press the wall jambs flush against the walls. See steps 5, 6, 7, 8, and 9. |
| Symptom: Water Leaks | Recommended Action |
| 1. Water leaks between panels. | A. When showering, make sure the inside panel is against the showerhead wall. |
| 2. Water leaks between the wall jamb and the door panel. | A. Adjust the door panel to line up with the wall jamb. See step 17. |
| 3. Water leaks under the bottom track. | A. Check for proper silicone sealant application. See steps 21, 22, and 23. Apply more silicone sealant in the leak location. |
| Symptom: Operation (open/close) | Recommended Action |
| 1. The outside panel is difficult to move. | A. Ensure a gap exists between the bottom track and the door panel. If no gap exists, lower the rollers to the next hole. |
| | B. Ensure the rollers are properly installed. See step 12. |
| | C. Clean any debris in the top track groove. |
| 2. The inside panel is difficult to move. | A. Ensure a gap exists between the bottom track and the door panel. If no gap exists, lower the rollers to the next hole. |
| | B. Ensure the rollers are properly installed. See step 10. |
| | |

C. Clean any debris in the top track groove.

WARRANTY

5 YEARS LIMITED

SP2375, 5100 Series, 5300 Series, 5400 Series, 6300 Series, 6500 Series

3 YEARS LIMITED

1500 Series, 1900 Series, 2200 Series, 5900 Series

1 YEAR LIMITED

500 Series, 600 Series, 660 Series, 670 Series, 690 Series, 950 Series, 2300 Series, 3100 Series Based on the classification specified above, STERLING bath and shower doors are warranted to be free of

manufacturing defects within the time of the specified model's limited warranty from date of sale. Kohler Co. will, at its election, repair, rectify or replace a fixture when inspection by Kohler Co. discloses any such defects occurring in normal usage within the time period of coverage stated above. Kohler Co. is not responsible for

removal or installation costs where replacement is indicated. Damages due to improper handling, installation or maintenance are not considered manufacturing defects and are not covered by this warranty. This warranty is valid for the original, consumer purchaser only.

To obtain warranty service, contact Sterling, either through your plumbing contractor, home center, wholesaler or dealer, or by calling or writing Sterling, Consumer Services, 444 Highland Drive, Kohler, Wisconsin 53044,

TO THE EXTENT PERMITTED BY LAW, ALL IMPLIED WARRANTIES INCLUDING THOSE OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE HEREBY DISCLAIMED. KOHLER CO. AND SELLER HEREBY DISCLAIM ANY LIABILITY FOR SPECIAL, INCIDENTAL, OR CONSEQUENTIAL DAMAGES. Some states/provinces do not allow limitations on how long an implied warranty lasts, or the exclusion or limitation of special, incidental or consequential damages, so these limitations and exclusions may not apply to you. This warranty gives you specific legal rights. You may have other rights which vary from state/province to state/province.

This is the exclusive written warranty for Kohler Co.